

Inspection Report

Disclaimer: We are not professional inspection company. We use this report to tell client what we saw and what we have checked.

Basic Information					
Client		Product photo			
P/O Number					
Product Name	Vape Bag				
Model Number	-				
Order Quantity	600				
Supplier Name					
Date of Inspection	02.04.2018				
Inspection Summary					
Part A	Quantity	PASS			
Part B	Specifications	PASS			
Part C	Workmanship(AQL)	FAIL			
Part D	Measurement	/			
Part E	Mark & Packaging	/			
Remarks:					
Video Report Link		https://youtu.be/stpylnvVT0M			
Part A - Quantity					
Model Number	Order quantity	Packed Quantity			
	600	600pcs without package			

How we check the quantity?

1-Count one by one

Remarks:

Each row is 50pcs, 4 rows each box, 3 boxes; total is 600pcs

Part B - Specifications

Client provides the specifications. We check all points one by one.

Product Photos



Top View



Bottom View





Left View Right View





Back View Inside View

Part C - Workmanship (AQL)

Inspection Standard: AQL: Critical (0); Major (2.5); Minor (4.0)

Sampling Plan Link

Customer provides instructions on what needs to be checked.

Defect Descrtiption	Photo Number	Defective Classification		
		Critical	Major	Minor
Bad Inside Stitch		All		
Unstraight Zipper Alignment		All		
Unstraight pocket				16
Untrimmed edge				6
Long thread				5
Uncovered edge				3
Sample Size		80		
Total Defective Found				30
AQL Allowed		0	5	7

Defective Photos

https://drive.google.com/drive/folders/1yX1yav6HXPvhpW2KaEHjlzEqQSFlWyrg?usp=sharing

Bad Inside Stitch





Unstraight Zipper Alignment





Unstraight Zipper Alignment





Untrimmed Edge





Long Thread





Uncovered Edge





Part D - Measurements

Measure point	Required	Sample #1	Sample #2	Sample #3
LxWxH(cm)	/			
Weight	/			

Remarks				
Part E - Label and Package				
Product Marking	No package			
Label	N/A			
Barcode	No package			
Instruction Manual	N/A			
Carton size & Weight	No package			
Shipping Marks	/			
Remarks	/			